

# PLUMBING - SERVICE 13

- An unchecked box indicates that this feature was not inspected, not applicable, not required or not found.  
 This feature was inspected, working properly or needs some action - **X** indicates feature was NOT working as intended, needs immediate attention or is highlighted for your information.

**STRATA** Many elements are maintained by Strata and may not have been fully accessible or inspected

## WATER HEATER

N/A

- Appears Functional  No water  No Power or Fuel

**Location:**  Utility Room  Basement  Crawlspace  Garage (must be 18" above floor)  Closet  Exterior access

**Make** KCN MORE **Est. Age** 2009 **Estimated Capacity** 272.5 Litres - ~~Gallons~~ **Fuel Source**  Nat. Gas  Electric  Oil  LPG **Temp °F** 128

#1 \_\_\_\_\_ Litres - Gallons  Nat. Gas  Electric  Oil  LPG  \_\_\_\_\_

#2 \_\_\_\_\_ Litres - Gallons  Nat. Gas  Electric  Oil  LPG  \_\_\_\_\_

- Water shut-off valve\***  installed  corroded  handle missing  Tank covered with thermal wrap
- Vacuum release valve**  installed  not provided  Missing fire door cover  Improve access
- Pressure relief valve**  installed  not provided  handle missing  Hot water circulating system
- Discharge line**  installed  not provided  Recommend extension of pipe to within 6" of floor for safety
- Vent pipe flue**  installed  openings noted  loose  damaged  deteriorated sections  backdrafting noted
- Overflow pan**  No  Yes >> **Pan drains to:**  Floor drain  Crawlspace  In-house drain  Pump  Sump
- Flower drain**  Yes  Not visible (see note 2)  No Pilot  No Power  No gas drip leg  Negative slope on flue
- Corrosion inlet / outlet  No tape noted at inlet-to-tank connection - Dielectric reaction (corrosion) is possible
- Older unit(s) may have limited life - failure probability increases with age  Leaking  Rusting  Corroded  Scorched
- Heaters are often guaranteed for 5 - 10 years but typically last 9 - 14 years  Improper clearance to combustibles (6" min. required)

## MAIN ENTRANCE LINE

- Appears Functional  Not found

- Supply Lines**  Public  Private  Strata **Material:**  Plastic (PVC, -PB, -Pex)  Copper  Galvanized
- Main Valve Location**  Basement or Crawlspace  Beside or behind water heater  Under stairwell  Front  Side  Rear
- Interior Diameter**  1/2"  3/4"  1"  Pressure regulator not visible  Copper Pipe - no protection from concrete
- Shut-off Valve\***  installed  unable to locate  leaking  corroded  broken handle  non-operational  poor location
- Water Pressure (PSI) 68 @ 1200 (above 80 PSI is high and adjustment is suggested)  Pressure not tested
- Mobile Home - It is recommended that heat tape is tested and replaced on a regular basis \* Shut-off valves are not tested

## SUPPLY PIPES

- Appears Functional  Not fully visible  Freeze vulnerable pipes - ie. outside wall, irrigation, attic

- Galvanized ( \_\_\_ % / feet)  Plastic (PVC - PB - CPVC) (see note 11)  PEX  Copper  Black Pipe (gas service)  Brass
- Corrosion / Rust  Leaks  Insufficient support  Unprotected pipe - subject to physical damage  Poor workmanship
- Dielectric fittings needed  Water hammer  Dissimilar metals in contact - recommend correction (hangers) (connections)
- Loss of water flow noted when two or more fixtures are used (typical when 1/2" service lines are used)
- There are some old water lines in service which affect water pressure in dwellings of this age (replacement may be necessary)
- Cross connections** possible at:  Laundry sink  Pool  Irrigation  Wet Bar  Bidet (check backflow valve)  Bathtub
- Gas meter:**  cannot tested by home inspectors **Location**  Front  Back  Side (of building) **Line marking**  not continuous

## Water Heater - Supply Service

- NO UTILITY PAN** was noted under the water heater. Moisture damage to adjacent area is possible if tank, pipes or valves leak.
- NO FLOOR DRAIN** was visible near the water heater. Moisture damage to the adjacent area is possible if tank, pipes or valves leak. Suggest the addition of a moisture alert alarm, water ejection pump or improved drainage system.
- DRAIN WATER HEATERS** on a regular basis to expel sediment from the tank. This extends the life of the tank and makes it more cost-efficient to operate.
- A **SAFE TEMPERATURE** for hot water is 120 - 130° F. Even though this is a 'relatively-safe' temperature, the human pain threshold is around 110 to 115° F. Over 140° F can scald.
- CORROSION AT WATER HEATER** inlet or outlet piping. This could indicate a leak or could be the result of a di-electric reaction between dissimilar metals - use a plumbers tape on connections.
- WATER SOFTENER** Verify with the current owner on the operation of this component. Testing water softeners and timers is beyond the scope of a CAHPI inspection.
- WATER HEATER** could not be fully inspected:  
 pilot not lit  no power or gas  no water
- WATER PRESSURE IS OVER 80 PSI.** Pressures above 80 psi may void appliance warranties or damage valves for some appliances such as water heaters, toilets or washing machines. Flexible supply lines to washing machines, toilets, dishwashers, etc. are more likely to burst with higher pressures. Recommend reducing pressure to 40 - 80 psi. or replaced with metal flexible hoses
- UNSUPPORTED SUPPLY PIPES** were noted - stress may cause these pipes to leak. Support with hangers of same material, i.e., copper pipe with copper hangers, PVC with PVC hangers.
- WATER INLET AND MAIN VALVE** was not found as it was probably hidden behind something or not otherwise visible. Suggest locating and marking this shutoff valve after moving in as a safety concern.
- SOME ABS/PB** (polybutylene) plastic piping systems (some have plastic connections) may have documented defects. Contact manufacturer's plumbing expert for further information and evaluation. Monitor connections for leaks.
- SPRINKLERS (in-house, ceiling and yard systems), WATER SOFTENERS and WATER FILTERS** are not part of a regular home inspection.
- An inspection of **POOLS AND HOT TUBS** could take several hours and is beyond the scope of a CAHPI inspection. Pools and hot tubs without water or power cannot be tested for circulation nor can operation of heaters or pumps be confirmed.
- DAMAGED FLOORING** was noted under the water heater but is now dry. This may be from a previous leak; however, strength of the floor material may have been jeopardized.
- GAS WATER HEATER IN A BEDROOM CLOSET** should have weatherstripping around perimeter of the cover door to prevent gas fumes from entering the bedroom. Electric heaters are OK and require no special enclosures.